



Edifica Colombia Ltda
 Cra 48 No. 98-57
 Bogotá D.C. Colombia
 Telephone: (057) 5086013
 Fax: (057) 2362121

BORING NUMBER BH-06

CLIENT SPIA - SOCIEDAD PUERTO INDUSTRIAL AGUADULCE PROJECT NAME PUERTO AGUADULCE
 PROJECT NUMBER 13016 PROJECT LOCATION AGUADULCE, BUENAVENTURA, COLOMBIA
 DATE STARTED 16/5/13 COMPLETED 22/5/13 GROUND ELEVATION -11.5 m 0 HOLE SIZE HQ
 DRILLING CONTRACTOR Edifica Colombia Ltda GROUND WATER LEVELS:
 DRILLING METHOD Drilling with TP-50D AT TIME OF DRILLING --- 11.0m
 LOGGED BY Roberto Nieves CHECKED BY Luis F Vesga AT END OF DRILLING --- 11.0m
 NOTES Offshore borehole AFTER DRILLING ---

GEOTECHBHPLOTS GEOTECHNICAL INVESTIGATION FOR SPIA. TEST BORINGS LOGS.GPJ GINT STD CANADA LAB.GDT 25/6/13

DEPTH (m)	GRAPHIC LOG	MATERIAL DESCRIPTION	SAMPLE TYPE NUMBER	RECOVERY % (RQD)	BLOW COUNTS (N VALUE)	POCKET PEN. (kPa)	DRY UNIT WT. (Mg/m ³)	SPT N VALUE	
								PL	LL
		(CL-ML) Silty CLAY, dark gray, low plasticity, moist, organic, wood fragments	SPT 1	100	1-1-1 (2)			20	80
2		(CL-ML) Silty CLAY, dark gray, low plasticity, moist, organic, wood fragments	SPT 2	100	1-1-1 (2)			20	80
		No recovery. Very soft material	SH 3						
4		(CL-ML) Silty CLAY, dark gray, low plasticity, moist	SPT 4	100	1-1-1 (2)			20	80
		No recovery. Soft material	SH 5						
6		(ML) Sandy SILT, dark gray, moist, low plasticity	SPT 6	100	1-1-1 (2)			20	80
8		(ML) Sandy SILT, dark gray, moist, low plasticity	SPT 7	100	1-1-1 (2)			20	80
10		(CL-ML) Clayey SILT, dark gray, moist, low plasticity	SPT 8	100	1-1-1 (2)			20	80

(Continued Next Page)



EDIFICA
COLOMBIA LTDA

GEOTECHNICAL INVESTIGATION FOR SPIA.
BOREHOLE BH-06

PHOTOGRAPHIC RECORD ROCK CORES





EDIFICA
COLOMBIA LTDA

GEOTECHNICAL INVESTIGATION FOR SPIA.
BOREHOLE BH-06



Preliminary