



Edifica Colombia Ltda
 Cra 48 No. 98-57
 Bogotá D.C. Colombia
 Telephone: (057) 5086013
 Fax: (057) 2362121

TEST PIT NUMBER TP-36

CLIENT SPIA - SOCIEDAD PUERTO INDUSTRIAL AGUADULCE PROJECT NAME PUERTO AGUADULCE
 PROJECT NUMBER 13016 PROJECT LOCATION AGUADULCE, BUENAVENTURA, COLOMBIA
 DATE STARTED 30/5/13 COMPLETED 30/5/13 GROUND ELEVATION _____ TEST PIT SIZE _____
 EXCAVATION CONTRACTOR Edifica Colombia Ltda GROUND WATER LEVELS:
 EXCAVATION METHOD Backhoe AT TIME OF EXCAVATION ---
 LOGGED BY Juan Carlos Vergara CHECKED BY Luis F Vesga AT END OF EXCAVATION ---
 NOTES _____ AFTER EXCAVATION ---

DEPTH (m)	SAMPLE TYPE NUMBER	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION	
2		CH		0.20 (CH) CLAY, brown, roots presence, high plasticity, low moisture	
		CH		(CH) CLAY ocher, high plasticity, low moisture	
		CH		0.60	(CH) CLAY, gray, orange veins, high plasticity, low moisture
		CH		0.85	(CH) CLAY, gray, orange veins, high plasticity, low moisture
		CH		1.30	(CH) CLAY, gray, orange veins, high plasticity, low moisture
		ML		(ML) SILT, dark gray (saprolite)	
				2.00	

Bottom of test pit at 2.00 meters.

Preliminary