



Edifica Colombia Ltda
 Cra 48 No. 98-57
 Bogotá D.C. Colombia
 Telephone: (057) 5086013
 Fax: (057) 2362121

TEST PIT NUMBER TP-41

CLIENT SPIA - SOCIEDAD PUERTO INDUSTRIAL AGUADULCE **PROJECT NAME** PUERTO AGUADULCE

PROJECT NUMBER 13016 **PROJECT LOCATION** AGUADULCE, BUENAVENTURA, COLOMBIA

DATE STARTED 27/5/13 **COMPLETED** 27/5/13 **GROUND ELEVATION** _____ **TEST PIT SIZE** _____

EXCAVATION CONTRACTOR Edifica Colombia Ltda **GROUND WATER LEVELS:**

EXCAVATION METHOD Backhoe **AT TIME OF EXCAVATION** ---

LOGGED BY Juan Carlos Vergara **CHECKED BY** Luis F Vesga **AT END OF EXCAVATION** ---

NOTES _____ **AFTER EXCAVATION** ---

DEPTH (m)	SAMPLE TYPE NUMBER	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
		CH		(CH) CLAY, ocher, high plasticity, low moisture
		CH		(CH) CLAY, ocher, orange veins, high plasticity, low moisture
		CH		(CH) CLAY, gray, ocher veins, high plasticity, low moisture
2		CL		(CL) CLAY, gray, orange veins, low to high plasticity, low moisture
		ML		(ML) SILT, dark gray, low plasticity, damp
				3.50

Bottom of test pit at 3.50 meters.

GENERAL BH / TP / WELL / GEOTECHNICAL INVESTIGATION FOR SPIA. TEST BORINGS LOGS.GPJ GINT STD CANADA LAB.GDT 18/6/13

Preliminary