Edifica Colombia Ltda
Cra 48 No. 98-57
Bogotá D.C. Colombia
Telephone: (057) 5086013
Fax: (057) 2362121

TEST PIT NUMBER TP-43

CLIENT SPIA - SOCIEDAD PUERTO INDUSTRIAL AGUADULCE
PROJECT NAME PUERTO AGUADULCE
PROJECT NUMBER 13016
PROJECT LOCATION AGUADULCE, BUENAVENTURA, COLOMBIA
DATE STARTED 26/5/13 **COMPLETED** 26/5/13
GROUND ELEVATION _____ **TEST PIT SIZE** _____
EXCAVATION CONTRACTOR Edifica Colombia Ltda
GROUND WATER LEVELS:
EXCAVATION METHOD Backhoe
AT TIME OF EXCAVATION ---
LOGGED BY Juan Carlos Vergara **CHECKED BY** Luis F Vesga
AT END OF EXCAVATION ---
NOTES _____
AFTER EXCAVATION ---

DEPTH (m)	SAMPLE TYPE NUMBER	U.S.C.S.	GRAPHIC LOG		MATERIAL DESCRIPTION
		CH		0.38	(CH) CLAY, brown, roots presence, low moisture, high plasticity
		CH		0.80	(CH) CLAY, ocher, orange veins, low moisture, high plasticity
		CH		1.00	(CH) CLAY, yellow,low moisture, high plasticity
		CH		1.50	(CH) CLAY, gray, high plasticity, low moisture
2		ML		3.00	(ML) SILT, dark gray, low plasticity, damp

Bottom of test pit at 3.00 meters.

Preliminary