






Edifica Colombia Ltda
 Cra 48 No. 98-57
 Bogotá D.C. Colombia
 Telephone: (057) 5086013
 Fax: (057) 2362121

TEST PIT NUMBER TP-05

CLIENT SPIA - SOCIEDAD PUERTO INDUSTRIAL AGUADULCE PROJECT NAME PUERTO AGUADULCE
 PROJECT NUMBER 13016 PROJECT LOCATION AGUADULCE, BUENAVENTURA, COLOMBIA
 DATE STARTED 17/5/13 COMPLETED 17/5/13 GROUND ELEVATION _____ TEST PIT SIZE _____
 EXCAVATION CONTRACTOR Edifica Colombia Ltda GROUND WATER LEVELS:
 EXCAVATION METHOD Backhoe AT TIME OF EXCAVATION ---
 LOGGED BY Juan Carlos Vergara CHECKED BY Luis F Vesga AT END OF EXCAVATION ---
 NOTES _____ AFTER EXCAVATION ---

DEPTH (m)	SAMPLE TYPE NUMBER	U.S.C.S.	GRAPHIC LOG	MATERIAL DESCRIPTION
		CH		(CH) CLAY, ocher, roots presence, high plasticity, moist
		CH		(CH) CLAY, yellow, gray and brown veins, high plasticity, dry
2		ML		(ML) Sandy SILT, gray, low plasticity, low moisture
				Bottom of test pit at 3.00 meters.

GENERAL BH / TP / WELL GEOTECHNICAL INVESTIGATION FOR SPIA. TEST BORINGS LOGS.GPJ GINT STD CANADA LAB.GDT 18/6/13

Preliminary